Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Kathigenahalli and Main overhead Tank Near -

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Kattigenahalli 2nd Main overhead Tank

Near





Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.



Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.



Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Scanned by CamScanner

Scanned by CamScanner

Scanned by CamScanner

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Noor Nayeem



Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Kadigenahalli Chowdi Layout

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-24

29.12.18

Scanned by CamScanner

- Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Shivapura 5th cross

Byrathanna layout Installed Pump

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Kr. Shamanayana (Kaththyenahalli)

Sri Pathapi Nayak
1st cross

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Ardu Nus Vinyakanagar

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Scanned by CamScanner

Maintenance of Existing Borewells in Ward No. 05 Bytarayanapura Sub Division.

Babu Nagar